# Oil Field Environmental Incident Summary

**Responsible Party:** CONTINENTAL RESOURCES, INC. **Well Operator:** CONTINENTAL RESOURCES, INC.

Well Name: WINCHESTER 43-8SH

Field Name: CEDAR HILLS Well File #: 27121

Date Incident:8/26/2015Time Incident:10:00Facility ID Number:County:BOWMANTwp: 132Rng: 106Sec: 8Qtr:

Location Description: Leaked occurred on Kinder Morgan's Bradac Compressor Station. Fluid then

ran off the edge of the Compressor Station site.

Submitted By: Patrick Skillestad Received By:

Contact Person: Patrick Skillestad

PO BOX 268870

OKLAHOMA CITY, OK 73126

General Land Use: Other - Described Above Affected Medium: Topsoil

**Distance Nearest Occupied Building:** 

Distance Nearest Water Well:

Type of Incident Pipeline Leak

Release Contained in Dike No Reported to NRC: No

|       | Spilled | Units   | Recovered | Units   | Followup | Units   |
|-------|---------|---------|-----------|---------|----------|---------|
| Oil   | 1       | Barrels | 1         | Barrels | 1        | barrels |
| Brine | 9       | Barrels | 9         | Barrels | 9        | barrels |

Other

**Description of Other Released Contaminant:** 

Inspected: Written Report Received: 9/14/2015 Clean Up Concluded: 8/27/2015

Risk Evaluation:

None

Areal Extent:

200 ft x 50 ft

## Potential Environmental Impacts:

Gravel and dirt on Compressor Station and topsoil in pasture off location.

### Action Taken or Planned:

Flow line will be repaired. Visually contaminated material will be removed and disposed of.

Wastes Disposal Location: Little Missouri Special Landfill

Agencies Involved:

### **Updates**

Date: 8/27/2015 Status: Reviewed; Followup Required Author: Stockdill, Scott

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

#### Notes:

According to the incident summary, this spill impacted areas off of location. Followup is necessary.